Coventry

Belgotex*























Stain Resistant

Antistatic

Environmentally

Responsible

DS - R10 Suitable For Slip Resistance Underfloor Heating

Construction	Luxury Floating Flooring, Rigidcore
Plank Size	222.25mm x 1517.65mm
Tiles per Carton	6pcs / 2.02m ²
Total Weight	10148g/m²
Wearlayer Thickness	0.55mm
Total Thickness	6.5mm (5mm + 1.5mm Acoustic Backing)
Slip Resistance	DS R10 (EN 13893)
Fire Rating	CRF 8.8kW/m² (ISO 9239-1)
Underfloor Heating	Suitable - See installation instructions for more information.
Wet Areas	Suitable (ISO 4760:2022)
Dimensional Stability	0.08% (ISO 23999:2008)
Acoustic Properties	BCA Approved for High Rise Buildings
Impact Insulation Class	IIC = 51, ΔL_W = 19, L_{lin} = 9 (AS ISO 140.6-2006 / AS ISO 140.8-2006 / AS ISO 717-2-2004)
Residual Indentation	≤0.7% (ASTM F1914-11)
Resistance to Light	Pass (ASTM F1515-15)
Formaldehyde Group	E1 (EN 717-1)
Resistance to Staining	Excellent (EN 423)
Abrasion Resistance	Group T (EN 660)
Classification	Heavy Duty Residential / Heavy Duty Commercial
Stair Rating	Suitable
Warranty	20 Year Residential Warranty / 10 Year Commercial Warranty
Environmental	ISO 14001
Installation	Please contact Gilt Edge Industries for installation instructions. Must be laid in accordance with AS/NZ Installation Standards.

- For samples, range and warranty details please contact us on 0800 377 753 or belgotex.co.nz
- Specifications are based on averages from manufacturing processes and may vary within normal industry tolerances.
- This product is intended for use solely as an indoor floor covering and is not recommended or sold for any other purpose.
- Use entryway systems outside each entrance to prevent dirt, sand, grit and other substances from being tracked onto floor.
- Rubber Migration: Rubber migration (also known as Plasticiser Migration) is a condition that can cause vinyl to discolour. It is caused by rubber or latex products, eg rubber or latex-soled slippers, shoes and rubber backed mats, coming to contact with the vinyl over a constant period of time. It is neither a manufacturing nor an installation fault and therefore is not covered by our warranties.