



Construction	Classenboard HDF, High-density fibreboard (ML 2.0)
Locking System	Megaloc®
Surface Protection	Aluminum Oxide
Finish	Embossed in Register
Plank Size	243mm x 2175mm
Tiles per Carton	4pcs / 2.114m ²
Total Weight	1353g/m ²
Total Thickness	12mm
Wear Layer Thickness	0.1mm
Slip Resistance	DS (EN 13893)
Electrical Propensity	≤2kV (EN 1815)
Fire Rating	Cfl - S1 (EN 13501-1)
Surface Soundness	≥1.25N/mm ² (EN 311)
Thermal Insulation	≤0.15W/mK (EN 12667)
Underfloor Heating	Suitable
Wet Areas	Not Suitable
Residual Indentation	≤0.05mm (EN ISO 24343-1)
Light Fastness	≥4 (EN 20105-A02)
Formaldehyde Group	E1 (EN 717-1)
Resistance to Staining	5 (group 1 and 2), 4 (group 3) - (EN 438)
Wear Resistance	IP ≥6000 cycles (AC5) - (EN 13329)
Castor Chair Resistance	no damage with type W after 25 000 cycles (EN 425)
Impact Resistance	Small - diameter ball ≥ 15 N / Large - diameter ball ≥ 1000 mm (EN 133329)
Thickness Swelling	≤15% (EN 13329)
Locking Strength	F _{10.2} ≥1.0kN/mm / F _{50.2} ≥2.0kN/mm (ISO 24334)
Movement of a Furniture Leg	No damage with type 0 (EN 424)
Abrasion Grade	AC 5
Classification	Class 33 Commercial Heavy
Stair Rating	Suitable
Warranty	20 Year Residential Warranty / 10 Year Commercial Warranty
Environmental	Blue Angel Certified GREENGUARD Gold Certification A+ Emissions EN 14041

Installation Please contact Gilt Edge Industries for all trim, underlay and installation recommendations.
NB: If appropriate trims or underlays are not used, claims will not be accepted.
Must be laid in accordance with AS/NZ Installation Standards.

- For samples, range and warranty details please contact us on 0800 377 753 or belgotex.co.nz
- Specifications are based on averages from manufacturing processes and may vary within normal industry tolerances.
- This product is intended for use solely as an indoor floor covering and is not recommended or sold for any other purpose.
- Use entryway systems outside each entrance to prevent dirt, sand, grit and other substances from being tracked onto floor.
- **Rubber Migration:** Rubber migration (also known as Plasticiser Migration) is a condition that can cause vinyl to discolour. It is caused by rubber or latex products, eg rubber or latex-soled slippers, shoes and rubber backed mats, coming to contact with the vinyl over a constant period of time. It is neither a manufacturing nor an installation fault and therefore is not covered by our warranties.