Primero II

Belgotex[®]

Suitable For Underfloor Heating Suitable for Wet Areas Slip Resistant Castor Chair Compatible (only when glued down	SuperCuard Stain Shield a
Construction	Luxury Vinyl Tile
Plank Size	163mm x 988mm
Tiles per Carton	24pcs / 3.87m ²
Total Weight	3726g/m ²
Wearlayer Thickness	0.30mm
Total Thickness	2.25mm
Bevel	4-sided micro-bevel
Surface Protection	Superguard®
Slip Resistance	Pattern Slip Resistance (DIN 51130, AS NZS 4586:2013) Evergreen Oak 22937 R9 / P3 Major Oak 24847 R10 / P2 Major Oak 24982 R10 / P2 Major Oak 24942 R10 / P2 Summer Oak 24137 R10 / P2 Summer Oak 24243 R10 / P2 Summer Oak 2435 R10 / P2
Electrical Propensity	<2kV (EN 1815)
Electrical Resistance	≤10 ⁹ Ohm (ISO 1081)
Fire Rating	CRF 9.6kW/m ² (ISO 9239-1)
Acoustic Insulation	4dB (EN 140-8)
Dimensional Stability	≤0.05% (ISO 23999)
Thermal Insulation	≤0.25W/m/K (EN 12524)
Thermal Resistance	0.01m ² K/W (ISO 12664)
Underfloor Heating	Suitable, max 27°C (EN 12524)
Wet Areas	Suitable (ISO 4760:2022)
Residual Indentation	≥0.10mm (ISO 24343-1)
Colour Fastness	≥6 (ISO 105-B02)
Formaldehyde Group	E1 (EN 717-1)
Classifications	Class 23 Domestic Heavy / Class 31 Commercial Light
Warranties	LVT Warranty 20 Year Residential Warranty 10 Year Commercial Warranty
Environmental	Greentag Certified, BREEAM certified (ENP 461) FloorScore®, A+ Emissions
Installation	Please contact Gilt Edge Industries for all adhesive and installation instructions. NB: If recommended adhesive is not used, claims will not be accepted. Must be laid in accordance with AS/NZ Installation Standards. ase contact us on 0800 377 753 or belgotex.co.nz

■ For samples, range and warranty details please contact us on 0800 377 753 or belgotex.co.nz

Specifications are based on averages from manufacturing processes and may vary within normal industry tolerances.

This product is intended for use solely as an indoor floor covering and is not recommended or sold for any other purpose.

• Use entryway systems outside each entrance to prevent dirt, sand, grit and other substances from being tracked onto floor.

Rubber Migration: Rubber migration (also known as Plasticiser Migration) is a condition that can cause vinyl to discolour. It is caused by rubber or latex products, eg rubber or latex-soled slippers, shoes and rubber backed mats, coming to contact with the vinyl over a constant period of time. It is neither a manufacturing nor an installation fault and therefore is not covered by our warranties.