



Construction	Luxury Vinyl Tile
Plank Size	Classic: 196mm x 1320mm London Plank: 94mm x 282mm
Tiles per Carton	Classic: 14pcs / 3.62m ² London Plank: 92pcs/2.44m ²
Total Weight	4059g/m ²
Wearlayer Thickness	0.55mm
Total Thickness	2.5mm
Bevel	V-groove, 4-sided bevel
Surface Protection	Superguard®
Slip Resistance	R9 (AS NZS 4586:2013)
Electrical Propensity	<2kV (EN 1815)
Electrical Resistance	≤10 ⁹ Ohm (ISO 1081)
Fire Rating	CRF 9.0kW/m ² (ISO 9239-1)
Acoustic Insulation	4dB (EN 140-8)
Dimensional Stability	≤0.05% (ISO 23999)
Thermal Insulation	≤0.25W/m/K (EN 12524)
Thermal Resistance	0.01m ² K/W (ISO 12664)
Underfloor Heating	Suitable, max 27°C (EN 12524)
Residual Indentation	≥0.10mm (ISO 24343)
Colour Fastness	≥6 (ISO 105-B02)
Formaldehyde Group	E1 (EN 717-1)
Classifications	Class 23 Domestic Heavy / Class 33 Commercial Heavy / Class 42 Industrial Medium
Warranties	LVT Warranty 20 Year Residential Warranty 10 Year Commercial Warranty
Environmental	BREEAM certified (ENP 461) Indoor Air Quality - adheres to German AgBB Standards.
Installation	Please contact Gilt Edge Industries for all adhesive and installation instructions. NB: If recommended adhesive is not used, claims will not be accepted. Must be laid in accordance with AS/NZ Installation Standards.

- For samples, range and warranty details please contact us on 0800 377 753 or belgotex.co.nz
- Specifications are based on averages from manufacturing processes and may vary within normal industry tolerances.
- This product is intended for use solely as an indoor floor covering and is not recommended or sold for any other purpose.
- Use entryway systems outside each entrance to prevent dirt, sand, grit and other substances from being tracked onto floor.
- **Rubber Migration:** Rubber migration (also known as Plasticiser Migration) is a condition that can cause vinyl to discolour. It is caused by rubber or latex products, eg rubber or latex-soled slippers, shoes and rubber backed mats, coming to contact with the vinyl over a constant period of time. It is neither a manufacturing nor an installation fault and therefore is not covered by our warranties.