



Construction	Acoustic Luxury Vinyl Tile	
Plank Size	178mm x 1220mm	
Tiles per Carton	10pcs / 2.17m ²	
Total Weight	8400g/m ²	
Wearlayer Thickness	0.70mm	
Total Thickness	5.0mm	
Bevel	V-groove, 4-sided bevel	
Surface Protection	Superguard®	
Slip Resistance	Pattern	Slip Resistance (oil-wet ramp, AS NZS 4586:2013)
	European Oak 2870	R9
	European Oak 2951	R9
	Riviera Oak 1240	R10
	Swedish Pine 2242	R9
	Swedish Pine 2965	R9
	Traditional Oak 1826	R10
	Traditional Oak 1832	R10
Electrical Propensity	<2kV (EN 1815)	
Electrical Resistance	≤10 ⁹ Ohm (ISO 1081)	
Fire Rating	CRF 8.7kW/m ² (ISO 9239-1)	
Acoustic Insulation	ΔLw = 8 dB (EN ISO 10140-3)	
Dimensional Stability	≤0.10% (ISO 23999)	
Thermal Insulation	0.25w/(m.K) (EN 12524)	
Thermal Resistance	0.0223m ² .K/W (EN 12664)	
Underfloor Heating	Suitable, max 27°C (EN 12524)	
Residual Indentation	≤0.10mm (ISO 24343-1)	
Colour Fastness	≥6 (ISO 105-B02)	
Formaldehyde Group	E1 (EN 717-1)	
Classifications	Class 23 Domestic Heavy / Class 34 Commercial Very Heavy / Class 43 Industrial Heavy	
Warranties	LVT Warranty 20 Year Residential Warranty 10 Year Commercial Warranty	
Environmental	Indoor Air Quality - adheres to German AgBB Standards.	
Installation	Please contact Gilt Edge Industries for all adhesive and installation instructions. NB: If recommended adhesive is not used, claims will not be accepted. Must be laid in accordance with AS/NZ Installation Standards.	

- For samples, range and warranty details please contact us on 0800 377 753 or belgotex.co.nz
- Specifications are based on averages from manufacturing processes and may vary within normal industry tolerances.
- This product is intended for use solely as an indoor floor covering and is not recommended or sold for any other purpose.
- Use entryway systems outside each entrance to prevent dirt, sand, grit and other substances from being tracked onto floor.
- **Rubber Migration:** Rubber migration (also known as Plasticiser Migration) is a condition that can cause vinyl to discolour. It is caused by rubber or latex products, eg rubber or latex-soled slippers, shoes and rubber backed mats, coming to contact with the vinyl over a constant period of time. It is neither a manufacturing nor an installation fault and therefore is not covered by our warranties.