

GTI EL5 Connect



Construction	Conductive Interlocking Vinyl Tile
Tile Size	635mm x 635mm
m² Per Tile	0.403m ² (sold as individual tiles)
Pattern Repeat	No repeat
Total Weight	9240g/m ²
Wear Layer Thickness	2.0mm
Total Thickness	6.0mm
Surface Treatment	Evercare
Slip Resistance - Oil Wet Ramp	R9 (DIN 51130)
Slip Resistance - Wet Pendulum	P2 (AS 4586-2013, App A)
Electrical Propensity	< 2kV (EN 1815) <100V (IEC 61340-4-5, ESD shoes)
Electrical Resistance	Electrical Resistance $5 \times 10^4 < Rt \leq 10^6$ (EN 1081) Rgp < 10^9 (IEC 61340-4-1) Rg < 10^9 (IEC 61340-4-5) $2.5 \times 10^4 < Rgp < 10^9$ (ANSI/ESD STM 7.1) Protection Against Electrostatic Discharges OK (ANSI/ESD S20.20, IEC 61340-5-1)
Wear Resistance	Wear Resistance $\leq 4\text{mm}^3$ (EN 660.2)
Wear Group	P (QB30)
Fire Rating	CRF 9.6kW/m ² (ISO 9239-1)
Type Binder Content	I (EN ISO 10582)
Dimensional Stability	$\leq 0.25\%$ (EN ISO 23999)
Thermal Conductivity	0.25W/mK EN ISO 10456
Indoor Air Quality	TVOC after 28 days <10 $\mu\text{g}/\text{m}^3$ (ISO 16000-6) FloorScore®
Colour Fastness	≥ 6 (EN ISO 105 - B02)
Chemical Resistance	Good (EN ISO 26987)
Classification	Class 34 Commercial Very Heavy Class 43 Industrial Heavy
Warranties	12 Year Commercial Warranty
Installation	All tiles to be laid in the same direction. Please contact Gilt Edge Industries for all adhesive and installation instructions. NB: If recommended adhesive is not used, claims will not be accepted. Must be laid in accordance with AS/NZ Installation Standards
Environmental	100% REACH Compliant Floorscore ISO 14001 Environmental Product Declaration

- For samples, range and warranty details please contact us on 0800 377 753 or belgotex.co.nz
- Specifications are based on averages from manufacturing processes and may vary within normal industry tolerances.
- This product is intended for use solely as an indoor floor covering and is not recommended or sold for any other purpose.
- Use entryway systems outside each entrance to prevent dirt, sand, grit and other substances from being tracked onto floor.
- Rubber Migration: Rubber migration (also known as Plasticiser Migration) is a condition that can cause vinyl to discolour. It is caused by rubber or latex products, eg rubber or latex-soled slippers, shoes and rubber backed mats, coming to contact with the vinyl over a constant period of time. It is neither a manufacturing nor an installation fault and therefore is not covered by our warranties.
- Plain, granite or patterned vinyls will either need to be reverse laid or a wider width should be used to allow for colour inequality, an additional allowance may have to be made for the pattern repeat.

Belgotex®

A world of
perfect choices_