

# Mipolam EL5



<b>Construction</b>	Conductive Homogeneous Sheet Vinyl
<b>Width</b>	2.0m
<b>Standard Roll Length</b>	20m
<b>Pattern Repeat</b>	Random repeat, directional laying
<b>Total Weight</b>	2985g/m <sup>2</sup>
<b>Wear Layer Thickness</b>	2.0mm
<b>Total Thickness</b>	2.0mm
<b>Surface Protection</b>	Evercare™
<b>Slip Resistance - Oil-Wet Ramp</b>	R9 (EN 16165:2021, Annex B)
<b>Slip Resistance - Wet Pendulum</b>	P2 (AS 4586:2013, App A)
<b>Electrical Resistance</b>	10 <sup>4</sup> ≤ Rt ≤ 10 <sup>6</sup> Ohms (EN 1081)
<b>Electrical Propensity</b>	<2kV (EN 1815) <100V (IEC 61340-4-5, ESD shoes)
<b>Protection Against Electrostatic Discharges</b>	OK ANSI/ESD S20.20 OK (IEC 61340-5-1)
<b>Fire Rating</b>	CRF 8.6kW/m <sup>2</sup> (ISO 9239-1)
<b>Wear Resistance</b>	≤4mm <sup>3</sup> (EN 660.2)
<b>Wear Group</b>	P (NF 189)
<b>Type Binder Content</b>	I (EN ISO 10581)
<b>Dimensional Stability</b>	≤0.40% (EN ISO 23999)
<b>Thermal Conductivity</b>	0.25W/mK (ISO 10456)
<b>Indoor Air Quality</b>	TVOC after 28 days <10µg/m <sup>3</sup> (ISO 16000-6) FloorScore®
<b>Residual Indentation</b>	~0.02mm (EN ISO 24343-1)
<b>Colour Fastness</b>	≥6 (EN ISO 105 - B02)
<b>Chemical Resistance</b>	OK (EN ISO 26987)
<b>Anti-bacterial activity (E.coli – S. aureus – MRSA)</b>	> 99 % inhibits growth
<b>Classification</b>	Class 34 Commercial Very Heavy Class 43 Industrial Heavy
<b>Warranties</b>	12 Year Commercial Warranty
<b>Installation</b>	Cove fillet is required on all installations. Please contact Gilt Edge Industries for all adhesive and installation instructions. NB: If recommended adhesive is not used, claims will not be accepted. Must be laid in accordance with AS/NZ Installation Standards.

**Environmental** 100% Recyclable  
Environmental Product Declaration



- For samples, range and warranty details please contact us on 0800 377 753 or belgotex.co.nz
- Specifications are based on averages from manufacturing processes and may vary within normal industry tolerances.
- This product is intended for use solely as an indoor floor covering and is not recommended or sold for any other purpose.
- Use entryway systems outside each entrance to prevent dirt, sand, grit and other substances from being tracked onto floor.
- Rubber Migration: Rubber migration (also known as Plasticiser Migration) is a condition that can cause vinyl to discolour. It is caused by rubber or latex products, eg rubber or latex-soled slippers, shoes and rubber backed mats, coming to contact with the vinyl over a constant period of time. It is neither a manufacturing nor an installation fault and therefore is not covered by our warranties.
- Plain, granite or patterned vinyls will either need to be reverse laid or a wider width should be used to allow for colour inequality, an additional allowance may have to be made for the pattern repeat.

# Belgotex®

A world of  
perfect choices\_