



Construction	Classenboard HDF, High-density fibreboard (ML 2.0)
Locking System	Megaloc® Aqua Protect
Surface Protection	Isowaxx®
Finish	Embossed
Plank Size	192mm x 1285mm
Tiles per Carton	8pcs / 1.973m ²
Total Weight	7096g/m ²
Total Thickness	8.0mm
Wear Layer Thickness	0.1mm
Slip Resistance	DS (EN 13893)
Electrical Propensity	≤2kV (EN 1815)
Fire Rating	CRF ≥4.5kW/m ² (ISO 9239-1)
Surface Soundness	≥1.25N/mm ² (EN 311)
Thermal Insulation	≤0.07W/mK (EN 12667)
Underfloor Heating	Suitable
Wet Areas	Suitable (ISO 4760:2022)
Residual Indentation	≤0.05mm (EN ISO 24343-1)
Light Fastness	≥4 (EN ISO 4892-2)
Formaldehyde Group	E1 (EN 717-1)
Resistance to Staining	5 (group 1 and 2), 4 (group 3) - (EN 438)
Wear Resistance	IP ≥4000 cycles (AC4) - (EN 13329 Annex E)
Castor Chair Resistance	no damage with type W after 25 000 cycles (EN 425)
Impact Resistance	Small - diameter ball ≥ 12 N / Large - diameter ball ≥ 750 mm (EN 133329 Annex H)
Thickness Swelling	≤12% (ISO 24336)
Locking Strength	F _{10.2} ≥1.0kN/mm / F _{50.2} ≥2.0kN/mm (ISO 24334)
Movement of a Furniture Leg	No damage with type O (EN 424)
Abrasion Grade	AC 4
Classification	Class 32 Commercial Medium
Stair Rating	Suitable
Warranty	20 Year Residential Warranty / 10 Year Commercial Warranty
Environmental	Blue Angel Certified GREENGUARD Gold Certification A+ Emissions EN 14041
Installation	Please contact Gilt Edge Industries for all trim, underlay and installation recommendations. NB: If appropriate trims or underlays are not used, claims will not be accepted. Must be laid in accordance with AS/NZ Installation Standards.

- For samples, range and warranty details please contact us on 0800 377 753 or belgotex.co.nz
- Specifications are based on averages from manufacturing processes and may vary within normal industry tolerances.
- This product is intended for use solely as an indoor floor covering and is not recommended or sold for any other purpose.
- Use entryway systems outside each entrance to prevent dirt, sand, grit and other substances from being tracked onto floor.
- Rubber Migration: Rubber migration (also known as Plasticiser Migration) is a condition that can cause vinyl to discolour. It is caused by rubber or latex products, eg rubber or latex-soled slippers, shoes and rubber backed mats, coming to contact with the vinyl over a constant period of time. It is neither a manufacturing nor an installation fault and therefore is not covered by our warranties.