Spirit

Belgotex*















Warranty













Construction	Rigid Hybrid Floor
Finish	Embossed in Register Mantel Oak 8594 and Vintage Steel 0143 only Embossed
Plank Size	234.9mm x 1517.6mm
Tiles per Carton	6pcs / 2.14m ²
Total Weight	9820g/m²
Wear Layer Thickness	0.55mm
Total Thickness	6.0mm
Surface Protection	High Performance PU
Slip Resistance	R10 (EN 13893)
Electrical Propensity	≤2kV (EN 1815)
Fire Rating	CRF ≥11.0kW/m² (ISO 9239-1)
Acoustic Insulation	18dB (EN 10140)
Dimensional Stability	≤0.25% (ISO 23999)
Thermal Conductivity	0.128 (W/m*K) (EN 12664)
Indoor Air Quality	FloorScore® A+ Emissions Eurofins Gold Certified
Underfloor Heating	Suitable, maximum 27° C
Resistance to Staining	Group 1 + 2: Grade 5 / Group 3: Grade 4 (EN 438-2)
Wear Resistance	≥4000 cycles (EN 13329 Method A)
Castor Chair Resistance	≥ 25000 Cycles no damage (EN 425)
Impact Resistance	≥ 1800 mm (Large Diameter) (EN 13329 Annex F)
Locking Strength	Short Side: ≥ 3.5 kN/m/ Long Side: ≥ 2.0 kN/m (ISO 24334)
Movement of a Furniture Leg	No visible damage (EN 424)
Classification	Class 23 Domestic Heavy/ Class 34 Commercial Very Heavy
Stair Rating	Suitable
Warranty	20 Year Residential Warranty / 10 Year Commercial Warranty
Environmental	Greentag Certified Environmental Product Declaration GREENGUARD Gold Certification Declare ISO 9001, ISO 45001, ISO 14001
Installation	Please contact Gilt Edge Industries for all trim, underlay and installation recommendations. NB: If appropriate trims or underlays are not used, claims will not be accepted. Must be laid in accordance with AS/NZ Installation Standards.

- For samples, range and warranty details please contact us on 0800 377 753 or belgotex.co.nz
- Specifications are based on averages from manufacturing processes and may vary within normal industry tolerances.
- This product is intended for use solely as an indoor floor covering and is not recommended or sold for any other purpose.
- Use entryway systems outside each entrance to prevent dirt, sand, grit and other substances from being tracked onto floor.
- Rubber Migration: Rubber migration (also known as Plasticiser Migration) is a condition that can cause vinyl to discolour. It is caused by rubber or latex products, eg rubber or latex-soled slippers, shoes and rubber backed mats, coming to contact with the vinyl over a constant period of time. It is neither a manufacturing nor an installation fault and therefore is not covered by our warranties.

