

Taralay Premium Acoustic



| | |
|---|---|
| Construction | Heterogeneous Sheet Vinyl |
| Width | 2.0m |
| Standard Roll Length | 25m |
| Total Weight | 2800g/m ² - 3260g/m ² |
| Wear Layer Thickness | >1.0mm |
| Total Thickness | 3.0mm - 3.3mm |
| Surface Protection | Evercare™ |
| Slip Resistance - Oil Pendulum | R9 (AS 4586:2013, App D) |
| Slip Resistance - Wet Pendulum | P4 (AS 4586-2013, App A) |
| Electrical Propensity | ≤ 2kV (EN 1815) |
| Fire Rating | CRF 5.8kW/m ² (ISO 9239-1) |
| Acoustic Insuation | 17dB (ISO 717-2) - Osmoz, Indiana, Brazilia, Poesy, Neopolis 16dB (ISO 717-2) - Metallica |
| Wear Resistance | ≤2mm ³ (EN 660.2) |
| Wear Group | T (NF 189) |
| Dimensional Stability | ≤0.40% (EN ISO 23999, EN 434) |
| Thermal Insulation | 0.25W/mK (ISO 10456) |
| Indoor Air Quality | TVOC after 28 days <10µg/m ³ (ISO 16000-6) FloorScore® |
| Anti-bacterial Activity (E. coli - S. aureus – MRSA) | > 99% inhibits growth (ISO 22196) |
| Residual Indentation (requirement) | ≤0.20mm (EN ISO 24343-1, EN 433) |
| Residual Indentation (average value measured) | ≈0.06mm |
| Colour Fastness | ≥6 (EN 20 105 - B02) |
| Chemical Resistance | OK (EN ISO 26987) |
| Classification | Class 34 Commercial Very Heavy Class 42 Industrial Medium |
| Warranties | 12 Year Commercial Warranty |
| Installation | Cove Fillet or Pencil Cove is recommended on all installations. Please contact Gilt Edge Industries for all adhesive and installation instructions. NB: If recommended adhesive is not used, claims will not be accepted. Must be laid in accordance with AS/NZ Installation Standards. |

Environmental Greentag Certified



- For samples, range and warranty details please contact us on 0800 377 753 or belgotex.co.nz
- Specifications are based on averages from manufacturing processes and may vary within normal industry tolerances.
- This product is intended for use solely as an indoor floor covering and is not recommended or sold for any other purpose.
- Use entryway systems outside each entrance to prevent dirt, sand, grit and other substances from being tracked onto floor.
- Rubber Migration: Rubber migration (also known as Plasticiser Migration) is a condition that can cause vinyl to discolour. It is caused by rubber or latex products, eg rubber or latex-soled slippers, shoes and rubber backed mats, coming to contact with the vinyl over a constant period of time. It is neither a manufacturing nor an installation fault and therefore is not covered by our warranties.
- Plain, granite or patterned vinyls will either need to be reverse laid or a wider width should be used to allow for colour inequality, an additional allowance may have to be made for the pattern repeat.

Belgotex®

A World of Perfect Choices